

Ron Broas • Director of Facilities 99 Myers Corners Road, RCK Annex, NY 12590 • (845) 298-5150 x42110 • Fax (845) 298-5138

DATE: March 26, 2021
TO: Dwight Bonk
FROM: Ronald Broas

SUBJECT: Fire Safety Inspection

The annual safety inspection for the school district buildings was conducted on January 13, 2021. The inspection was performed by Bruce Bingham & Associates, a New York State code enforcement officer.

The following facilities received no non-conformance citations:

Administrative Office for the Wappingers Central School District Facilities & Operations Office Building/Central Warehouse Fishkill Elementary Portable Building Fishkill Plains Bus Garage Gayhead Modulars John Jay Concession Stand and Field Storage John Jay Dugouts John Jay Storage Buildings (old sewer plant) Main Bus Garage #1 Main Bus Garage #2 Oak Grove Art Center Orchard View Alternative High School Roy C. Ketcham Concession Stand

A list of non-conformances cited and their dispositions are listed below; all non-conformances have been corrected. There are no outstanding non-conformances items at this time.

Brinckerhoff Elementary School

1 02E-2 Windows are obstructed

Roy C. Ketcham Field Storage Building

Roy C. Ketcham Green House Van Wyck Driver Check-in Building

James Evans Elementary School

1 02E-2 Windows are obstructed

Fishkill Elementary School

- 1 02E-2 Windows are obstructed
- 2 12J-1 Extension cords are not properly used and are not a substitute for permanent wiring.

Fishkill Plains Elementary School

1 02E-2 Windows are obstructed

Gayhead Elementary School

1 16B-2 Portable fire extinguishers are not located in a conspicuous location.

John Jay High School

1 10A-2 Fire safety and evacuation plans are not in place.

Kinry Road Elementary School

1 02E-2 Windows are obstructed

Myers Corners Elementary School

1 02E-2 Windows are obstructed

Oak Grove Elementary School

1 16B-2 Portable fire extinguishers are not located in a conspicuous location.

Roy C. Ketcham High School

- 1 10A-2 Fire safety and evacuation plans are not in place.
- 2 12E-1 Electric Hazard
- 3 12J-1 Extension cords are not properly being used.
- 4 16B-2 Portable fire extinguishers are not located in a conspicuous location.

Sheafe Road Elementary School

1 16B-2 Portable fire extinguishers are not located in a conspicuous location.

Van Wyck Junior High School

1 12E-1 Electric Hazard

Vassar Road Elementary School

1 16B-2 Portable fire extinguishers are not located in a conspicuous location.

Wappingers Junior High School

1 16B-2 Portable fire extinguishers are not located in a conspicuous location.